




## Structurally Deficient Bridges on the National Highway System Massachusetts - Congressional District 05



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 187 structurally deficient NHS bridges in Massachusetts, 11 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

<b>Bridge Label</b>	<b>Structure ID</b>	<b>Bridge Description</b>	<b>Location Description</b>
1	H090201V7MHDNBI	I 495 SB	3 MI NE RT 117
2	L1302227LMHDNBI	I 495 SB	2MI.NTH.OF ST.111
3	L1302227KMHDNBI	I 495 NB	2 MI.NTH.OF ST.111
4	M10007288MHDNBI	ST 27 /ST62/WALTHM	0.1 MI E RT 62
5	W1100126RMHDNBI	US 20 BOSTN PST RD	0.75 MI. WST. OF ST-27
6	C190212DTMHDNBI	ST 2 CONCORD TPK	1.75 MI SE RT 2 ROTARY
7	L150882M4MHDNBI	HWY WOOD ST EXT	ROURKE BRIDGE
8	L150722HAMHDNBI	HWY WB LOWLL CON	0.1 MI E RT 110 & PLAIN
9	L150722H9MHDNBI	HWY EB LOWLL CON	0.1 MI E RT 110 & PLAIN
10	L150322FRMHDNBI	HWY BRIDGE ST	0.4 KM S RTE 110 & 38
11	M170012YLMHDNBI	ST 28 BROADWAY	.9 MI S ST213
12	A090342XUMHDNBI	I 495 SB	1.4 MI N I-93
13	L040012YHMHDNBI	ST 28 BROADWAY	AT MERRIMAC RIVER
14	H1200730YMHDNBI	ST125 BRIDGE ST	.3 MI E HAVERHILL CENTER
15	G1500130EMHDNBI	ST 97 /ST113/LNCLN	AT MERRIMAC RIVER