




Structurally Deficient Bridges on the National Highway System Idaho - Congressional District 02



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 40 structurally deficient NHS bridges in Idaho, 1 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	21590	NHS 7433;VISTA AVE	IN BOISE;VISTA AVE.
2	12270	US 20 ;I 84B	IN BOISE;BROADWAY AVE
3	15750	I 84 EBL	1.3 E. BOISE
4	15755	I 84 WBL	1.3 E. BOISE
5	16180	I 84 EBL	3.6 N. TWIN FALLS
6	17890	US 93	4.5 N. SALMON
7	16390	I 84 EBL	7.9 E. BURLEY
8	16395	I 84 WBL	7.9 E. BURLEY
9	12025	I 15B	1.5 N. MCCAMMON
10	12370	US 20 WBL	2.5 N. IDAHO FALLS
11	13255	US 26	IN IDAHO FALLS