




Structurally Deficient Bridges on the National Highway System Michigan - Congressional District 02



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 261 structurally deficient NHS bridges in Michigan, 15 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	64164015000S060	US-31 SB	1.5 MI.N.W.OF SHELBY
2	64164015000S190	US-31 NB	4.0 MI N OF HART
3	61161075000S130	US-31 SB	0.6 MI S OF N JCT US-31BK
4	61161075000B050	US-31 SB	1.3 MI N OF S JCT US-31BR
5	03103032000B040	US-31 BR (RAMP)	S LTS OF HOLLAND
6	70170064000R014	I-96 WB	.4 MI NW OF M-104
7	70170024000S080	I-196 WB	4.4 MI NE I 96 BL
8	70170024000S070	I-196 EB	4.4 MI NE OF I 96 BL
9	83183032000B010	US-131	IN CADILLAC