




## Structurally Deficient Bridges on the National Highway System Michigan - Congressional District 13



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 261 structurally deficient NHS bridges in Michigan, 15 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	82182071000B040	M-85	IN DETROIT 10400 FORT ST
2	82182194000B010	I-75	IN DETROIT
3	82182123000S310	LIVERNOIS LEFT TUR	IN DETROIT
4	82182023000S138	I-94 TO W GR BLV R	IN DETROIT
5	82182194000S180	I-75 SB	IN DETROIT
6	82182023000S250	I-94EB RAMP TO M10	IN DETROIT RAMP B-G
7	82182251000S220	I-94 W-S RAMP	IN DETROIT
8	82182251000S180	I-75 SB EXIT RAMP	IN DETROIT
9	82182251000S160	WARREN AVE	IN DETROIT
10	82182251000S170	WARREN ENT TO I-75	IN DETROIT
11	82182251000S130	WILKINS ST & RAMP	IN DETROIT
12	82182024000S130	M-53(VANDYKE ST)	IN DETROIT
13	82182025000S010	M-3 (GRATIOT)	IN DETROIT