




Structurally Deficient Bridges on the National Highway System Minnesota - Congressional District 01



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



- Deficient Bridges
- City
- Interstate Highway
- Other NHS Highway
- Body of Water
- Urbanized Areas
- 11th Congressional District



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 47 structurally deficient NHS bridges in Minnesota, 1 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	67807	I 90 WB	2.0 MI E OF JCT TH 75
2	6889	US 71	1.0 MI SE OF JCT TH 60
3	74820	US 14 EB	AT THE S JCT TH 14
4	6808	I 90 EB	0.9 MI W OF W JCT TH 218
5	8929	I 90	0.5 MI W OF E JCT TH 218
6	6036	US 14	1.2 MI W OF W JCT TH 56
7	23006	US 63	1.7 MI N OF JCT CSAH 14
8	79009	US 61 SB	0.9 MI NW OF JCT TH 42
9	6461	US 61 NB	1.3 MI NW OF JCT TH 74
10	85808	I 90 EB	2.1 MI SE OF N JCT TH 61
11	85807	I 90 WB	2.1 MI SE OF N JCT TH 61
12	85810	I 90 EB	2.6 MI NW OF S JCT TH 61
13	85809	I 90 WB	2.6 MI NW OF S JCT TH 61
14	5475	US 61	0.1 MI E OF JCT TH 16