




Structurally Deficient Bridges on the National Highway System Missouri - Congressional District 09



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 125 structurally deficient NHS bridges in Missouri, 2 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	111	US 63 S	S 5 T 60 N R 14 W
2	6683	IS 70 E	S 2 T 48 N R 13 W
3	4738	US 63 S	S 14 T 47 N R 12 W
4	4659	US 63 N	S 29 T 45 N R 11 W
5	5090	US 54 E	S 13 T 51 N R 7 W
6	5390	MO 19 S	S 35 T 53 N R 7 W
7	1198	US 24 E	S 13 T 58 N R 6 W
8	6072	US 24 E	S 2 T 59 N R 5 W
9	11832	US 61 N	S 27 T 55 N R 4 W
10	5622	US 54 E	S 8 T 53 N R 2 W
11	4464	IS 44 W	S 34 T 41 N R 2 W
12	5204	US 54 E	S 34 T 54 N R 2 W