




Structurally Deficient Bridges on the National Highway System Nebraska - Congressional District 03



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 39 structurally deficient NHS bridges in Nebraska, 0 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	S385 07764	US385	4NW BRIDGEPORT
2	S083 14787	US83	0S THEDFORD
3	S006 10354	US6/US34	IN BARTLEY
4	S080 27711L	I80	2W MINDEN INTRCHG
5	S080 27711R	I80	2W MINDEN INTRCHG
6	S020 31087	US20/US275	2SE ONEILL
7	S034 22572L	WB-US34/SB-US281	0S GRAND ISLAND INTRCHG
8	S080 35312	SB-US81	YORK INTRCHG
9	S081 17727	US81	JCT US81/US20 3S
10	S081 20306	US81	12S YANKTON
11	S081 21468	US81	SCL YANKTON