




## Structurally Deficient Bridges on the National Highway System New York - Congressional District 17



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 227 structurally deficient NHS bridges in New York, 5 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

| Bridge Label | Structure ID | Bridge Description | Location Description      |
|--------------|--------------|--------------------|---------------------------|
| 1            | 5514182      | RTE I87            | 4.3 MI N JCT RTS I87+202  |
| 2            | 5514099      | RTE I87            | 2.6 MI E JCT RTS I-87<202 |
| 3            | 5514439      | RTE I87            | 1.2 MI W JCT SH 45 & I87  |
| 4            | 5025629      | RTE I87            | JCT OF RTS I87 & 45       |
| 5            | 5521257      | RTE 9A             | JCT SH 9A & HARLEM RIVER  |
| 6            | 2229530      | RTE 907V           | 2.4 MI NE H.HUDSON BR+9A  |
| 7            | 2230300      | RTE 908F           | .8 M N JCT I87&MOSHOLU PK |
| 8            | 5500529      | RTE 987D           | JCT OF RTS SMRP + CCP     |
| 9            | 1075049      | RTE 907H           | 4.4 MI N JCT I95 & BR PKY |
| 10           | 5500089      | RTE 907W           | 1.3 MI N JCT RTS HRP<1    |