




Structurally Deficient Bridges on the National Highway System



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode data from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 227 structurally deficient NHS bridges in New York, 5 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	1027840	RTE 60	11.1 MI S JCT RTS 60 & 83
2	5511512	RTE I90	4.3 MI SW OF SILVR CK INT
3	5511511	RTE I90	4.3 MI SW OF SILVR CK INT
4	5511521	RTE I90	3.3 MI SW OF SILVR CK INT
5	5511522	RTE I90	3.3 MI SW OF SILVR CK INT
6	6001320	RTE 5	.1 MI SW JCT SH5/US20&438
7	5060589	RTE 400	JCT RTS 400 + 240
8	1030240	RTE 78	.9 MI N JCT SH 78 & SH130