Note: The bridges displayed on this may represent the results of a combined ETS/RMA reflect to geocode bridges from the PRMAX believed Bridge seventry NRB. With the exception of Membridy and Presental values are commerciated as 250 et al. data is from the PRMAX believed Bridge deficient NRS bridges in Oiks, 7 could not be geologically because of insufficient data. Structurally deficient bridges are not necessarily umasky; all public read bridges receive segater andly inspections. One bridges lating were cologorated as instructurally deficient that the time the may not necessarily unasky;

Bridge Label	Structure ID	Bridge Description	Location Description
1	1804863	EXIT RAMP SN	1.73 MI. N. OF JCT. I-480
2	1806327	I-77	JCT. I-480