




Structurally Deficient Bridges on the National Highway System Ohio - Congressional District 17



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 17 structurally deficient NHS bridges in Ohio, 7 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	7705913	WB I-76	0.15 MI W OF SR 8
2	6729320	RAMP OVER TPK	AT EXIT 13
3	7800061	I80 TPK	0.4MI EAST OF EXIT 14
4	7804695	HIGHWAY	0.91 MI W OF SR 46
5	7804679	SR 82	1.30 MI W OF SR 46
6	7803427	E.B. IR80	0.29 MI W OF US 422
7	7808232	SR11	2.69 MI N OF SR 305
8	7803451	I-80	JCT IR 80 AND US 422
9	7803486	I-80	JCT IR 80 AND US 422
10	5006848	SILLIMAN ST (RAMP)	0.11 MI W OF SR 193
11	5004470	SR193	0.27 MI S OF US 422
12	7803842	IR 80 EAST BND	JCT IR 80 AND SR 193
13	7803877	I.R. 80 WEST BND	JCT IR 80 AND SR 193
14	7803931	HIGHWAY	0.37 MI E OF SR 193
15	5002133	MCGUFFEY STREET	0.25 MI E OF WICK AVE
16	5005310	US62	0.21 MI W OF US 62T
17	5005345	62	0.03 MI W OF US 62T
18	7804148	HIGHWAY	1.05 MI W OF US 62
19	7804172	HIGHWAY	1.05 MI W OF US 62
20	7804261	HIGHWAY	0.18 MI W OF US 62
21	5005523	US422	0.04 MI E OF SR 616
22	7804326	WB I 80	JCT OF IR 80 AND US 62